

Coupling - Compression w/Floloc 3/4 RG11207





Details

As cap is tightened, pressure causes the gripping ring to bite into the pipe eliminating pull out.

Specifications

Manufacturer Manufacturer's Model No Flo Control 112-07

Baber Turf Equipment Co. Unit 6 / 10 Firth Street Auckland, 2113

Unit 6 / 10 Firth Street Auckland, 2113 09 294 6040 https://baber.rrproducts.com/