



# NGK Spark Plug - TR5

RN2238



### Details

Replaces Champion RS14YC

### Replaces

AC Delco	C42CLTS, C42LTS, C43CLTS, MR43LTS, R42-5LTS, R42CLTS, R42LTS, R42LTSM, R43LTS, R43LTSM
Autolite	104, 105, 106, 3243, 3244, 3245, 3246, 3565, 3724, 765, 766, 865
Bosch	H6D, H6DC, H7D, H8DC, H8DC0, H8DCX, H9DC, H9DC0, HR8DC, HR8DCX, HR9D, HR9DC, HR9DCX
Champion	20, 408C2, 408S, 4408, 4408-2, BN12Y, BN7Y, BN89Y, RS12YC, RS13LYC5
Denso	T16NR-U11
MotorCraft	AGF22C, AGF32C, AGRF22, AGRF22C, AGRF32, AGRF42, AGRF52, AGSF22C, AGSF32C, AWRF32, AWRF42, AWSF22C, AWSF32, AWSF32C, AWSFA32C, SP415

### Specifications

Manufacturer	NGK
Box Quantity	4
Package Quantity	1

**Baber Turf Equipment Co.**

Unit 6 / 10 Firth Street Auckland, 2113

09 294 6040

<https://baber.rrproducts.com/>