



NGK Spark Plug - GR45GP

RN3142



Replaces

Autolite	AP646
Champion	3031, 3031-2

Specifications

Manufacturer	NGK
Box Quantity	4
Package Quantity	1

Baber Turf Equipment Co.

Unit 6 / 10 Firth Street Auckland, 2113
09 294 6040

<https://baber.rrproducts.com/>