



NGK Spark Plug - TR5GP

RN3186



Replaces

Autolite	AP104, AP105, AP106, AP5164
Bosch	HR8DPP30X, HR8LPP30U
Champion	3013, 3013-2, 3407, 7963, 7983
Denso	PT16TT

Specifications

Manufacturer	NGK
Box Quantity	4
Package Quantity	1

Baber Turf Equipment Co.

Unit 6 / 10 Firth Street Auckland, 2113
09 294 6040

<https://baber.rrproducts.com/>