



NGK Spark Plug - LZTR5AGP RN3381



Replaces

Autolite	AP5426
Bosch	HR8TPP3002V, HR9SPP300X
Champion	3570, 7032

Specifications

Manufacturer	NGK
Box Quantity	4
Package Quantity	1

Baber Turf Equipment Co.

Unit 6 / 10 Firth Street Auckland, 2113
09 294 6040

<https://baber.rrproducts.com/>