



NGK Spark Plug - UR5GP

RN3547



Replaces

Autolite	AP23, AP24, AP664
Champion	3018, 3018-2, 7018

Specifications

Manufacturer	NGK
Box Quantity	4
Package Quantity	1

Baber Turf Equipment Co.

Unit 6 / 10 Firth Street Auckland, 2113
09 294 6040

<https://baber.rrproducts.com/>