



NGK Spark Plug - BR6HS

RN3922



Replaces

AC Delco	R42CF, R42F
Autolite	3686
Bosch	WR7A, WR7AC
Champion	830, 931-1, 931M, 931S, 933-1, 933M, 933S, QL7J5, QL82C, QL86, QL86C, RL7J, RL82, RL85, RL86, RL86C
Denso	W20FSR, W20FSRU
R&R Products	R121-0547
Toro	121-0547

Specifications

Manufacturer	NGK
Box Quantity	10
Package Quantity	1

Fits Models

- Toro Greensmaster 1000
- Toro Greensmaster 1010
- Toro Greensmaster 1600
- Toro Greensmaster 1610
- Toro Greensmaster 800
- Toro Greensmaster Flex 1800
- Toro Greensmaster Flex 1820
- Toro Greensmaster Flex 2100
- Toro Greensmaster Flex 2120

Baber Turf Equipment Co.

Unit 6 / 10 Firth Street Auckland, 2113

09 294 6040

<https://baber.rrproducts.com/>