



NGK Spark Plug - LFR5AIX-11

RN4469



Replaces

Autolite	XP5325
Bosch	FR8MII33X
Champion	7975
Denso	IKH16, VKH16

Specifications

Manufacturer	NGK
Box Quantity	4
Package Quantity	1

Baber Turf Equipment Co.

Unit 6 / 10 Firth Street Auckland, 2113
09 294 6040

<https://baber.rrproducts.com/>