



NGK Spark Plug - R7435-10

RN4897



Replaces

Autolite	4051
----------	------

Specifications

Manufacturer	NGK
Box Quantity	4
Package Quantity	1

Baber Turf Equipment Co.

Unit 6 / 10 Firth Street Auckland, 2113
09 294 6040

<https://baber.rrproducts.com/>