



NGK Spark Plug - DPR9EA-9

RN5329



Replaces

Autolite	4162
Champion	8809, 8809-1, RAX92YC
Denso	X27EPR-U9

Specifications

Manufacturer	NGK
Box Quantity	10
Package Quantity	1

Baber Turf Equipment Co.

Unit 6 / 10 Firth Street Auckland, 2113
09 294 6040

<https://baber.rrproducts.com/>