



NGK Spark Plug - ZFR5FGP

RN7098



Replaces

Autolite	AP985
Bosch	FR8HPP30X, FR8LPP302X, FR8LPP30X
Champion	3318, 3318-2

Specifications

Manufacturer	NGK
Box Quantity	4
Package Quantity	1
Savings	Volume Buy

Baber Turf Equipment Co.

Unit 6 / 10 Firth Street Auckland, 2113

09 294 6040

<https://baber.rrproducts.com/>