


Replaces Exmark Metro Parts Walk Behind Mower - Model MGS481GKA322P0 with 32in



Walk Behind Mower - Model MGS481GKA322P0 with 32in Deck 32in Deck





Replaces Exmark Metro Parts Walk Behind Mower - Model MGS481GKA322P0 with 32in



Walk Behind Mower - Model MGS481GKA322P0 with 32in Deck 32in Deck

	R&R Part No.	OEM Part No.	Description	Qty Req	Order Quantity
Rotar	ry Blades				
1	R103-6581	103-6581	Mower Blade - 16-1/4 Mulch	2	
2	RRB3062-1600	103-6583, 103-6583-S	Mower Blade - High-Lift 16.25 x 2.5in x 5/8 Mt Hole	2	
			are manufactured in the USA with superior ruaranteed against defects in material and	allow	
3	RRB4062-1600	116-5178	Mower Blade - Mulcher 16.25 x 2.5in x 5/8 Mt Hole	2	
Belts					
20	R1-323734	1-323734	Drive Belt - Blades	1	
Othe	r Parts Available				
40	R103-8280	103-8280	Spindle Assy w/Bearings	2	
41	R103-2477	103-2477	Bearing - Jackshaft	4	
42	R103-1330	103-1330	Guard - Bearing - Top	2	
43	RC-10025	32120-8	Ring - Retaining	2	
44	R103-2535	103-2535	Spacer-Guard, Bottom	2	
45	R1-323529	1-323529	Tube - Spindle - Short	2	
46	R1-323539	1-323539	Spacer	8	
47	R1-513208	1-513208	Washer - Spring	2	
48	R1-800861	1-800861	Bolt - 5/8-18x8 Hex Hx GR5	2	
49	R400190	322-6	Bolt - Hex HD 5/16-18 x 1-1/4 GR5	8	
50	R445722	32128-20	Nut - Serrated Washer	22	
51	R106-5517	106-5517	Decal - Warning Hot Surface	2	

All original equipment manufacturers names and part numbers are used for identification purposes only, and we are in no way implying that our products are original equipment parts. Prices subject to change without notice.



Replaces Exmark Metro Parts Walk Behind Mower - Model MGS481GKA322P0 with 32in



Walk Behind Mower - Model MGS481GKA322P0 with 32in Deck 32in Deck

ltem R&R No Part No.	OEM Part No.	Description	Qty Req	Order Quantity
52 R103-2534	103-2534	Spacer - Bearing	0	
56 R282-2	1-303105	Yoke	1	
57 R32128-43	32128-43, 3290-357	Nut - Flanged Whiz - 3/8-16	8	
58 R98-5975	98-5975	Washer - Belleville	9	
59 R323-8	323-8	Bolt - Hex HD 3/8-16 x 1-1/2 GR8	8	