



Coupling - Compression w/Floloc 2

RG11220



Details

As cap is tightened, pressure causes the gripping ring to bite into the pipe eliminating pull out.

Specifications

Manufacturer

Flo Control



Baber Turf Equipment Co.

Unit 6 / 10 Firth Street Auckland, 2113
09 294 6040

<https://baber.rrproducts.com/>