



NGK Spark Plug - LZTR4AIX-11

RN2313



Replaces

Bosch

4482, HR9SII330X

Specifications

Manufacturer

NGK

Box Quantity

4

Package Quantity

1

Baber Turf Equipment Co.

Unit 6 / 10 Firth Street Auckland, 2113

09 294 6040

<https://baber.rrproducts.com/>