



NGK Spark Plug - WR5 RN2438



Replaces

AC Delco	83CTS, 83TS, 84TS, 85T, 85TS, 86TS, C85TS, R83CTS, R83TS, R84TS, R84TSX, R85TS, R86TS5
Autolite	156, 166, 3286, 34, 35, 36, 37, 44, 45, 46, 744, 745, 746, 747
Bosch	D10B, D10BC, D6B, D6BC, D7B, D7BC, D8A, D8AC, D8B, D8BC, D9B, D9BC, DR10B, DR10BC, DR6BC, DR7BC, DR8B, DR8BC, DR9B, DR9BC, M12B
Champion	11C2, 11S, 21, 21S, 22, 22S, 4011, 409, RF11YC, RF14YC, RF18YC, RF9YC
Denso	MA16P-U, MA16PR-U, MA16PR-U11, MA16PR-U15
MotorCraft	B82, BF22, BF22C, BF22CX, BF22X, BF32, BF32C, BF32CX, BF32X, BF42, BF42C, BF82C, BF92, BRF22, BRF22C, BRF32, BRF42, BRF82, BSF42C, BSF6, BSF82C, BSF92, BTF42, BTRF42

Specifications

Manufacturer	NGK
Box Quantity	4
Package Quantity	1

Baber Turf Equipment Co.

Unit 6 / 10 Firth Street Auckland, 2113
09 294 6040

<https://baber.rrproducts.com/>