



NGK Spark Plug - PFR5G-11

RN2647



Replaces

Champion	7071, 7346, 7546, RC10PYP4, RC10PYPB4, RC12PYP
Denso	PK16PR8
MotorCraft	AGSP32FP, AGSP32FPM, AGSP32PP

Specifications

Manufacturer	NGK
Box Quantity	4
Package Quantity	1

Baber Turf Equipment Co.

Unit 6 / 10 Firth Street Auckland, 2113
09 294 6040

<https://baber.rrproducts.com/>