



NGK Spark Plug - FR4GP RN2685



Replaces

AC Delco	41-808
----------	--------

Specifications

Manufacturer	NGK
Box Quantity	4
Package Quantity	1

Baber Turf Equipment Co.

Unit 6 / 10 Firth Street Auckland, 2113
09 294 6040

<https://baber.rrproducts.com/>