



NGK Spark Plug - TR4GP RN2815



Replaces

Bosch	HR9DPP30Y, HR9LPP30X
Champion	3013, 3015

Specifications

Manufacturer	NGK
Box Quantity	4
Package Quantity	1

Baber Turf Equipment Co.

Unit 6 / 10 Firth Street Auckland, 2113
09 294 6040

<https://baber.rrproducts.com/>