



NGK Spark Plug - UR45GP

RN3207



Replaces

Autolite	AP26, AP666
Bosch	HR9BPP30V
Champion	3025, 3025-2

Specifications

Manufacturer	NGK
Box Quantity	4
Package Quantity	1

Baber Turf Equipment Co.

Unit 6 / 10 Firth Street Auckland, 2113
09 294 6040

<https://baber.rrproducts.com/>