



NGK Spark Plug - BP4HS

RN3611



Details

Replaces Champion RL95YC

Replaces

Autolite	517
Champion	L15Y, L95Y
Denso	W14FP-L, W14FP-U, W14FP-UL, W14FPR
MotorCraft	AV82

Specifications

Manufacturer	NGK
Box Quantity	10
Package Quantity	1

Baber Turf Equipment Co.

Unit 6 / 10 Firth Street Auckland, 2113
09 294 6040

<https://baber.rrproducts.com/>