



NGK Spark Plug - BKR6EIX-11

RN3764



Replaces

Autolite	XP3923
Bosch	4417, FR6DPX, FR6K1133X, FR7DII33X , FR7DPX
Champion	3344-2
Denso	IK20, K20PR-TP11, K20PR-ZU11, K20R- ZU11, SVK20RZ11, VK20
MotorCraft	AGSP32P

Specifications

Manufacturer	NGK
Box Quantity	4
Package Quantity	1

Baber Turf Equipment Co.

Unit 6 / 10 Firth Street Auckland, 2113
09 294 6040

<https://baber.rrproducts.com/>