




# NGK Spark Plug - BR7HS

RN4122



## Details

Replaces Champion RL82C

## Replaces

AC Delco	R41CF, S42FR*
Autolite	3684
Bosch	WR5A, WR5AC
Champion	874, 874-1, 874C, 874M, 874S, RL4J, RL77J, RL78, RL78C, RL82C
Denso	TR22, W22FSR, W22FSR-U
MotorCraft	AER2X

## Specifications

Manufacturer	NGK
Box Quantity	10
Package Quantity	1

## Baber Turf Equipment Co.

Unit 6 / 10 Firth Street Auckland, 2113  
09 294 6040

<https://baber.rrproducts.com/>