



NGK Spark Plug - IZFR6H11

RN4294



Replaces

Bosch

FR7KPP332

Specifications

Manufacturer

NGK

Box Quantity

4

Package Quantity

1

Baber Turf Equipment Co.

Unit 6 / 10 Firth Street Auckland, 2113

09 294 6040

<https://baber.rrproducts.com/>