



NGK Spark Plug - LFR5AGP RN5018



Replaces

Bosch	FR8MPP30X
Denso	PKH16TT

Specifications

Manufacturer	NGK
Box Quantity	4
Package Quantity	1

Baber Turf Equipment Co.

Unit 6 / 10 Firth Street Auckland, 2113
09 294 6040

<https://baber.rrproducts.com/>