



NGK Spark Plug - BKR5EIX-11

RN5464



Replaces

Autolite	XP3924
Bosch	4418, FR8DII33X , FR8DPX, FR8KII33X , FR9DPV
Denso	IK16, K16PR-TP11, K16PR-ZU11, K16R- ZU11, SK16PR-E11, VK16

Specifications

Manufacturer	NGK
Box Quantity	4
Package Quantity	1

Baber Turf Equipment Co.

Unit 6 / 10 Firth Street Auckland, 2113
09 294 6040

<https://baber.rrproducts.com/>