



NGK Spark Plug - DP8EA-9

RN5829



Replaces

Autolite	4153
Champion	A6Y, A6YC
Denso	X24EP-U, X24EP-U9

Specifications

Manufacturer	NGK
Box Quantity	10
Package Quantity	1

Baber Turf Equipment Co.

Unit 6 / 10 Firth Street Auckland, 2113
09 294 6040

<https://baber.rrproducts.com/>