



NGK Spark Plug - DILFR6D11

RN6176



Replaces

Denso	FK20HR11
-------	----------

Specifications

Manufacturer	NGK
Box Quantity	4
Package Quantity	1

Baber Turf Equipment Co.

Unit 6 / 10 Firth Street Auckland, 2113
09 294 6040

<https://baber.rrproducts.com/>