



NGK Spark Plug - PLFR5A-11

RN6240



Replaces

Autolite	APP5325
Bosch	8110
Champion	7975
Denso	SK16HR-11

Specifications

Manufacturer	NGK
Box Quantity	4
Package Quantity	1

Baber Turf Equipment Co.

Unit 6 / 10 Firth Street Auckland, 2113
09 294 6040

<https://baber.rrproducts.com/>