



NGK Spark Plug - FR5AP-10

RN6371



Replaces

Champion	3340, 3340-2
Denso	K16PR-P11

Specifications

Manufacturer	NGK
Box Quantity	4
Package Quantity	1

Baber Turf Equipment Co.

Unit 6 / 10 Firth Street Auckland, 2113
09 294 6040

<https://baber.rrproducts.com/>