



NGK Spark Plug - TR55IX

RN7164



Replaces

AC Delco	12561466, 12563707, 12565753, 25332827, 25332828, 41-902, 41-913, 41-919, 41-929, 41-931, 41-932, 41-936, 41-942, 41-943, 41-947, 41-952, 41-974, 92108895, R44LTS6K, R45LTS6K
Autolite	XP605
Bosch	4458, 4459, HR8KII33V, HR8KII33Y, HR9DPY, HR9KII33Y
Champion	7401, 9404, RS14PYP6
Denso	IT16, TJ16R15
MotorCraft	AWSF32F, AWSF42EE

Specifications

Manufacturer	NGK
Box Quantity	4
Package Quantity	1

Baber Turf Equipment Co.

Unit 6 / 10 Firth Street Auckland, 2113
09 294 6040

<https://baber.rrproducts.com/>