



NGK Spark Plug - XR45IX

RN7293



Replaces

Autolite	AP847
Bosch	WR9FPY

Specifications

Manufacturer	NGK
Box Quantity	4
Package Quantity	1

Baber Turf Equipment Co.

Unit 6 / 10 Firth Street Auckland, 2113
09 294 6040

<https://baber.rrproducts.com/>