



# NGK Spark Plug - R5724-9

RN7891



### Replaces

Autolite	93
Champion	682, 683, 685, S57C, S59C, S59YC

### Specifications

Manufacturer	NGK
Box Quantity	4
Package Quantity	1

## Baber Turf Equipment Co.

Unit 6 / 10 Firth Street Auckland, 2113  
09 294 6040

<https://baber.rrproducts.com/>