




# NGK Spark Plug - R5672A-10

RN7942



## Replaces

Autolite	50
Champion	276, 791, C57Y, C57YC

## Specifications

Manufacturer	NGK
Box Quantity	4
Package Quantity	1

## Baber Turf Equipment Co.

Unit 6 / 10 Firth Street Auckland, 2113  
09 294 6040

<https://baber.rrproducts.com/>