




Replaces Toro Groundsmaster 4100-D Parts

Rotary Mower - Models 30604 & 30608
Right-Hand Deck Lift Arms and Spindle



All original equipment manufacturers names and part numbers are used for identification purposes only, and we are in no way implying that our products are original equipment parts. Prices subject to change without notice.



Replaces Toro Groundsmaster 4100-D Parts

Rotary Mower - Models 30604 & 30608
Right-Hand Deck Lift Arms and Spindle



Item No	R&R Part No.	OEM Part No.	Description	Qty Req	Order Quantity
---------	--------------	--------------	-------------	---------	----------------

Overhaul Kits

1	R110-8297	110-8297, 26-1830	Bearing Set w/Retaining Rings - Spindle	2	
2	R104-3549	104-3549	Spacer Set - Spindle Bearing	2	
3	R114-5620	114-5620	Seal Kit - Fits R127-3694 Hyd Motor	1	

Belts

20	R108-8077	105-7438, 108-8077	V-Belt - Deck	1	
----	-----------	-----------------------	---------------	---	--

Rotary Blades

30	R107-0215-03	107-0215-03	Mower Blade - Mulcher - 19 in	2	
----	--------------	-------------	-------------------------------	---	--

Detail Description: Mulching mower blades increase efficiency and productivity. The patented Faltor mulching "teeth" circulate cut grass back into the deck multiple times creating a finer cut and better looking turf.:

32	R106-7166-03	106-7166-03	Mower Blade - 19 Inch Combo	2	
60	R139-1035	104-3529, 119-4547, 139-1035	Drivin Spindle Assy	1	
61	R119-4776	104-3532, 119-4776	Spindle Assy	1	
62	R119-4546	104-3552, 119-3552, 119-4546	Spindle Housing Assy	1	
63	R119-4775	119-4775	Spindle Housing Assy	1	
70	R104-3554	104-3554	Shaft - Spindle Assy.	2	
<i>Tech Note: Ser# 313000001-316000501:</i>					
70	R139-1044	139-1044	Shaft - Spindle Assy	2	

All original equipment manufacturers names and part numbers are used for identification purposes only, and we are in no way implying that our products are original equipment parts. Prices subject to change without notice.



Replaces Toro Groundsmaster 4100-D Parts

Rotary Mower - Models 30604 & 30608
Right-Hand Deck Lift Arms and Spindle



Item No	R&R Part No.	OEM Part No.	Description	Qty Req	Order Quantity
<i>Tech Note: Ser# 405700000-999999999:</i>					
71	R92-9800	69-6950, 69-6980, 92-9800	Spacer - Spindle	2	
72	R253-154	253-154	Seal - Spindle	4	
73	R106-7159	106-7159	O-Ring	2	
74	R104-3545	104-3545	Pulley - Drive	1	
75	R104-3546	104-3546	Pulley - Lower Driven	1	
76	R104-8322	104-8322, 120-5576	Washer - Spindle Shaft Hardened	2	
77	R32127-46	32127-46, 3296-60	Locknut	2	
78	R104-3544	104-3544	Mount - Motor Drive	1	
79	R104-3541	104-3541	Hub - Drive	1	
80	R104-3542	104-3542	Spider	1	
81	R99-5489	99-5489	Hydraulic Motor	1	
81	R127-3694	127-3694	Hydraulic Motor	1	
82	R340-139	340-139	Hydraulic Fitting - 90 Deg	2	
83	R340-2	340-2, 60-1920	Hydraulic Fitting - Striaight	1	
84	R237-42	237-42, 31-4160	O-Ring	1	
85	R237-22	107-8844, 237-22, 237-78	O-Ring	1	
86	R237-65	237-65, 237.65	O-Ring	2	

All original equipment manufacturers names and part numbers are used for identification purposes only, and we are in no way implying that our products are original equipment parts. Prices subject to change without notice.



Replaces Toro Groundsmaster 4100-D Parts

Rotary Mower - Models 30604 & 30608
Right-Hand Deck Lift Arms and Spindle



Item No	R&R Part No.	OEM Part No.	Description	Qty Req	Order Quantity
87	R237-81	237-81, 237.81, 327-81	O-Ring	2	
88	R72-9361	27-1000, 27-1001, 72-9360, 72-9361	Cup - Anti-Scalp	2	
89	R92-5816	92-5816	Bolt - Hex HD 1/2-20 x 2-1/4	2	
90	R110-9596	110-9596, 132-9421	Pulley- Flat Idler	1	
91	R110-6128	110-6128	Idler Arm Assy	1	
92	R256-76	256-76	Bushing	2	
93	R302-5	21-6010, 302-11, 302-37, 302-47, 302-5, 302-57, 302-58, 302-6, 31-0300, 32-9660, 60-0800, 62-3880, 92-4181	Fitting - Grease	1	
95	R3-6498	3--6498, 3-6498, 47-8270	Washer - Thrust	1	
96	R458013	30-0580, 32120-72, 458013, 93-2525, 936125	Ring - Retaining	1	
97	R100-3102	100-3102	Washer-Flat	1	

All original equipment manufacturers names and part numbers are used for identification purposes only, and we are in no way implying that our products are original equipment parts. Prices subject to change without notice.



Replaces Toro Groundsmaster 4100-D Parts

Rotary Mower - Models 30604 & 30608
Right-Hand Deck Lift Arms and Spindle



Item No	R&R Part No.	OEM Part No.	Description	Qty Req	Order Quantity
99	R3253-7	01-166-0030, 01-166-0080, 01-166-0290, 01-166-0810, 23-13-GD, 3253-7, 48-9380	Washer - Lock 1/2	1	
100	R325-7	01-150-0380, 01-178-0814, 3226-3, 325-7, 48-9490	Bolt - 1/2-13 x 1 3/4 Hex HD Gr 5	1	
101	R107938	107938	Spring - Extension	1	
102	R68-0090	68-0090	Screw - Adjusting	1	
103	R104-0858	104-0858	Bolt - Shoulder	1	
104	R3296-56	3296-56	Nut - Lock - 1/4-20 ESNA Jam	1	
107	R323-6	01-150-0010, 01-178-0608, 20-47-AD, 20-47-AGD, 3224-2, 323-6, 49-3510, 908034P, 908332	Bolt - Hex HD 3/8-16 x 1 GR5 YZ	4	

All original equipment manufacturers names and part numbers are used for identification purposes only, and we are in no way implying that our products are original equipment parts. Prices subject to change without notice.



Replaces Toro Groundsmaster 4100-D Parts

Rotary Mower - Models 30604 & 30608
Right-Hand Deck Lift Arms and Spindle



Item No	R&R Part No.	OEM Part No.	Description	Qty Req	Order Quantity
108	R453011	01-166-0100, 01-166-0120, 01-166-0270, 01-166-0500, 01-166-0600, 01-166-0620, 132-4593, 2356-3, 237-12, 24-10-AD, 24-11-AD, 24-11-BD, 24-12-AD, 24-12-BD, 30-9310, 32-8190, 3256-24, 3256-3, 3256-36, 3256-4, 453011, 47-9950, 48-9220, 513458, 7-0052	Washer - Flat 3/8 SAE Y/Zinc	4	
109	R302-60	302-60	Zerk - Grease 90 Deg.	2	
110	R114-8195	114-8195, R & R ONLY	Bolt- Ribbed Neck	12	
112	R74-5950	249-48, 74-5950	Latch - Swell	4	
113	R93-7818	93-7818	Decal - Blade Torque	1	
114	R3234-42	3234-42	Bolt - 3/8-16 x 1 Hx HD Fl	2	
115	R104-8301	104-8301, 104-9301, 109-6658, 133-7570	Locknut - 3/8-16 Nylon Flanged	12	

All original equipment manufacturers names and part numbers are used for identification purposes only, and we are in no way implying that our products are original equipment parts. Prices subject to change without notice.