



## Replaces Exmark Lazer Z X-Series Parts

*Zero Turn Mower with 60in Deck - Models LZX801CKA60600,  
LZX801CKA606C1, LZX801GKA60600, LZX801GKA606C1,  
LZX921GKA60600, LZX940EKC60600, LZX940EKC606T0,  
LZX940EKC606W0  
60in Deck*

---




All original equipment manufacturers names and part numbers are used for identification purposes only, and we are in no way implying that our products are original equipment parts. Prices subject to change without notice.



# Replaces Exmark Lazer Z X-Series Parts

Zero Turn Mower with 60in Deck - Models LZX801CKA60600, LZX801CKA606C1, LZX801GKA60600, LZX801GKA606C1, LZX921GKA60600, LZX940EKC60600, LZX940EKC606T0, LZX940EKC606W0  
60in Deck



All original equipment manufacturers names and part numbers are used for identification purposes only, and we are in no way implying that our products are original equipment parts. Prices subject to change without notice.



# Replaces Exmark Lazer Z X-Series Parts

Zero Turn Mower with 60in Deck - Models LZX801CKA60600, LZX801CKA606C1, LZX801GKA60600, LZX801GKA606C1, LZX921GKA60600, LZX940EKC60600, LZX940EKC606T0, LZX940EKC606W0  
60in Deck



Item No	R&R Part No.	OEM Part No.	Description	Qty Req	Order Quantity
<b>Blades</b>					
1	<b>R103-6393</b>	103-6393	Mower Blade - 20-1/2 Mulching	3	
2	<b>RRB4065-2001</b>	116-5174, 116-5174-S	Mower Blade - Mulcher 20.5 x 2.5in x 15/16 Mt Hole	3	
3	<b>RRB3065-2001</b>	103-6403, 103-6403-S	Mower Blade - High-Lift 20.5 x 2.5in x 15/16 Mt Hole	3	
<b>Belts</b>					
20	<b>R135-5774</b>	135-5774	Belt - 5V	1	
<b>Other parts Available</b>					
40	<b>R109-9220</b>	109-9220	Bolt - Sems 1/2-20	3	
41	<b>R116-9362</b>	116-9362	Bolt - Hex HD 3/8-16 x 3 3/4 GR8 YZ	4	
42	<b>R103-8415</b>	103-8415	Roller - Anti Scalp	4	
68	<b>R116-6317</b>	116-0133, 116-6317	Spring - Extension	1	
70	<b>R109-7840</b>	109-7840	Adjuster - Lift - Deck	4	
71	<b>R443818</b>	3218-5	Nut - 1/2-13 Hex Jam Zinc	4	
72	<b>R104-8301</b>	104-8301, 109-6658	Locknut - 3/8-16 Nylon Flanged	31	
73	<b>R116-8131</b>	116-8131	Axle - Roller	3	
74	<b>R98-5975</b>	98-5975	Washer - Belleville	3	
75	<b>R109-7124</b>	109-7124	Spring - Extension	1	
76	<b>R109-6917</b>	109-6917	Spindle Housing Assy Complete with Spindle	3	

All original equipment manufacturers names and part numbers are used for identification purposes only, and we are in no way implying that our products are original equipment parts. Prices subject to change without notice.



## Replaces Exmark Lazer Z X-Series Parts

Zero Turn Mower with 60in Deck - Models LZX801CKA60600, LZX801CKA606C1, LZX801GKA60600, LZX801GKA606C1, LZX921GKA60600, LZX940EKC60600, LZX940EKC606T0, LZX940EKC606W0  
60in Deck



Item No	R&R Part No.	OEM Part No.	Description	Qty Req	Order Quantity
77	<b>R103-9539</b>	103-9539	Spindle Housing Assy with Bearings	3	
78	<b>R103-3037</b>	103-3037	Splined Bushing	3	
81	<b>R126-9196</b>	126-9196	Idler Pulley - Flat	1	
82	<b>R1-633456</b>	1-633456	Bushing - Idler	2	
83	<b>R116-4667</b>	126-7685	Idler -Pulley - Flat	2	
87	<b>R116-0797-03</b>	116-0797-03	Link-Lift - Deck	1	
88	<b>R116-0000</b>	116-0000	Spring - Extension	1	
89	<b>R32128-23</b>	32128-23, 99-5107	Nut - Lock Hex Flanged 1/2-13	12	
90	<b>R453022</b>	3256-28	Washer - 3/4 SAE	2	
91	<b>R116-2022</b>	116-2022	Shoulder Bolt - Flanged Hex Head	2	
92	<b>R109-7952</b>	109-7952	Deck Strut Assy	2	
93	<b>R109-5013</b>	109-5013	Panhard Rod Assy	1	
94	<b>R109-5010</b>	109-5010	Spacer	6	
95	<b>R109-5009</b>	109-5009	Bushing - Suspension - Rubber	6	
96	<b>R325-12</b>	325-12	Bolt - Hx HD	2	
97	<b>R3233-34</b>	3233-34	Carriage Bolt - 1/2-13 x 2 1/2 Grade 5	3	
98	<b>R325-17</b>	325-17	Bolt - Hex Head	1	
99	<b>R92-7674</b>	92-7674	Bolt - Shoulder	1	

All original equipment manufacturers names and part numbers are used for identification purposes only, and we are in no way implying that our products are original equipment parts. Prices subject to change without notice.