


Replaces Toro Greensmaster 3050 Parts



Dethatcher Unit - Model 04479 Rear Roller Brush





Replaces Toro Greensmaster 3050 Parts



Dethatcher Unit - Model 04479 Rear Roller Brush

	OEM Part No.	Description	Qty Order Req Quantity
R105-6792	104-1829, 105-6792	Brush - Rear Roller	1
R104-1830	104-1830	Bolt - J	2
R3296-2	32127-10, 3296-2, 9157404	Nut - #10 Lock	2
R105-5720	105-5720	Belt - Poly V	1
R251-259	251-259, 251-307	Bearing - Ball	1
R104-4727	104-4727	Ring - Retaining	1
R115-7143	115-7143	Spring - Wave	1
R112-6957	112-6957	Washer - Hardened	2
	R104-1830 R3296-2 R105-5720 R251-259 R104-4727 R115-7143	Part No. Part No. R105-6792 104-1829, 105-6792 R104-1830 104-1830 R3296-2 32127-10, 3296-2, 9157404 R105-5720 105-5720 R251-259 251-259, 251-307 R104-4727 104-4727 R115-7143 115-7143	Part No. Description R105-6792 104-1829, 105-6792 Brush - Rear Roller R104-1830 104-1830 Bolt - J R3296-2 32127-10, 3296-2, 9157404 Nut - #10 Lock R105-5720 105-5720 Belt - Poly V R251-259, 251-307 Bearing - Ball R104-4727 104-4727 Ring - Retaining R115-7143 115-7143 Spring - Wave