

Replaces Toro Reelmaster 6700D Parts



Traction Unit - Models 03808 & 03813 Traction Unit





Replaces Toro Reelmaster 6700D Parts



Traction Unit - Models 03808 & 03813 Traction Unit

	R&R Part No.	OEM Part No.	Description	Qty Order Req Quantity
Overl	haul Kits			
1	R125-1682	125-1682	Motor Seal Kit	1
	Tech Note: Used on	Hydraulic Motor Assem	bly No. 120-6272:	
Hose	S			
51	R105-7927	105-7927	Hydraulic Hose Assy	1
51	R105-9817	105-9817	Hydraulic Hose Assy	1
51	R92-7534	92-7534	Hydraulic Hose Assy	1
51	R92-7536	92-7536	Hydraulic Hose Assy	1
51	R92-7538	92-7538	Hydraulic Hose Assy	1
51	R92-7539	92-7539	Hydraulic Hose Assy	1
51	R98-4584	98-4584	Hydraulic Hose Assy	1
Othe	r Parts Available			
70	R110-1717	110-1717, 92-7387, 98-9999	Hydraulic Motor - Reel	1
	Tech Note: Fits Mod	dels 03802 / 03805 / 038	08 / 03813:	
71	R120-6272	120-6272	Hydraulic Motor	1
	Tech Note: Fits Mod			
72	R99-5608-03	99-5608, 99-5608-03	Spring-Torsion, RH	1
73	R99-5609-03	99-5609, 99-5609-03	Spring-Torsion, LH	1
74	R104-0015	104-0015, 104-8339	Bushing - Flanged	4

All original equipment manufacturers names and part numbers are used for identification purposes only, and we are in no way implying that our products are original equipment parts. Prices subject to change without notice.



Replaces Toro Reelmaster 6700D Parts



Traction Unit - Models 03808 & 03813 Traction Unit

Item R&R No Part No.	OEM Part No.	Description	Qty Order Req Quantity
75 R56-7972	56-7972	Clamp - Tube	4
76 R56-7976	56-7976	Clamp - Tube	2
77 R240-7	240-7	Grommet - Rubber - 2 in OD	1
78 R240-5	240-5	Grommet - Rubber	4
79 R106-6754	106-6754	Decal - Danger	1
80 R93-6696	93-6696	Decal - Warning	0
81 R106-9004	106-9004, 93-9173, 98-9976, 99-2480, 99-2484, 99-5605	Bumper - Rubber	0