




Replaces Toro Greensmaster 3050 Parts

Traction Unit - Model 04351

Steering Arm



All original equipment manufacturers names and part numbers are used for identification purposes only, and we are in no way implying that our products are original equipment parts. Prices subject to change without notice.



Replaces Toro Greensmaster 3050 Parts

Traction Unit - Model 04351

Steering Arm



| Item No | R&R Part No. | OEM Part No. | Description | Qty Req | Order Quantity |
|---------|--------------------|---|----------------------------------|---------|----------------|
| 1 | R49-5900 | 49-5900 | Steering Wheel | 1 | |
| 2 | R256-113 | 256-113 | Bushing - 3/4 ID x 1 1/8 Flange | 2 | |
| 3 | R32121-44 | 32121-44 | Roll Pin - 3/16 x 2 | 1 | |
| 4 | R95-7149 | 95-7149 | Front Steering Pulley | 1 | |
| 5 | R95-5965 | 95-5965 | Cable - Steering Fits 3050 | 1 | |
| 6 | R400124 | 01-178-0420, 20-11-AD, 321-15 | Bolt - Hex HD 1/4-20 x 2-1/2 GR5 | 1 | |
| 7 | R5-2653 | 5-2653 | Pulley - Idler Steering Cable | 4 | |
| 8 | R256-2 | 256-2 | Bushing - Idler Pulley | 4 | |
| 9 | R71-5440 | 71-5440 | Spacer - Steering Pulley | 2 | |
| 10 | R10-7240 | 10-7240 | Spacer - Steering Pulley | 1 | |
| 11 | R95-5959-01 | 95-5959, 95-5959-01 | Pulley - Support - Red | 1 | |
| 12 | R301504 | 2296-42, 301504, 32127-24, 32128-33, 32146-17, 3296-16, 3296-42, 3296-42, 915661P | Locknut - ESNA 1/4-20 | 1 | |
| 13 | R93-8063 | 83-1790, 93-8063 | Decal - Warning Ce | 1 | |

All original equipment manufacturers names and part numbers are used for identification purposes only, and we are in no way implying that our products are original equipment parts. Prices subject to change without notice.



Replaces Toro Greensmaster 3050 Parts

Traction Unit - Model 04351

Steering Arm



| Item No | R&R Part No. | OEM Part No. | Description | Qty Req | Order Quantity |
|---------|--------------|--|------------------------------|---------|----------------|
| 14 | R325-4 | 01-150-0280, 01-178-0806, 01-178-0808, 20-85-AD, 20-85-AGD, 325-1, 325-2, 325-4 | Bolt - Hex HD 1/2-13 x 1 | 4 | |
| 15 | R3256-26 | 01-166-0540, 01-166-0820, 17-2530, 24-13-BD, 30-8570, 3256-26, 356206, 48-9390 | Washer - 1/2 in | 4 | |
| 16 | R444850 | 3296-59 | Nut - 3/8-16 Jam Center Lock | 2 | |
| 17 | R453011 | 01-166-0100, 01-166-0120, 01-166-0270, 01-166-0500, 01-166-0600, 01-166-0620, 132-4593, 2356-3, 237-12, 24-10-AD, 24-11-AD, 24-11-BD, 24-12-AD, 24-12-BD, 30-9310, 32-8190, 3256-24, 3256-3, 3256-36, 3256-4, 453011, 47-9950, 48-9220, 513458, 7-0052 | Washer - Flat 3/8 SAE Y/Zinc | 4 | |
| 18 | R95-2932 | 95-2932 | Bracket - Pulley | 1 | |

All original equipment manufacturers names and part numbers are used for identification purposes only, and we are in no way implying that our products are original equipment parts. Prices subject to change without notice.



Replaces Toro Greensmaster 3050 Parts

Traction Unit - Model 04351

Steering Arm



| Item No | R&R Part No. | OEM Part No. | Description | Qty Req | Order Quantity |
|---------|--------------------|---|------------------------------|---------|----------------|
| 19 | R322-4 | 322-4, 3290-115, 908018P | Bolt - Hex HD 5/16-18 x 7/8 | 2 | |
| 20 | R3296-29 | 1-804256, 3290-357, 3296-29, 915662P | Locknut - 5/16-18 ESNA | 2 | |
| 21 | R95-2941-01 | 95-2941, 95-2941-01 | Steering Arm | 1 | |
| 22 | R95-7140P | 95-7140, 95-7140-01 | Cap - Plastic - Steering Arm | 1 | |

All original equipment manufacturers names and part numbers are used for identification purposes only, and we are in no way implying that our products are original equipment parts. Prices subject to change without notice.